

**Inspection Photos**  
**Location Name: LORENCITO 1-14-34-67**  
**API#: 05-071-07719**  
**INSP. #: 695101001**



**PHOTO 1: WELLHEAD**

**PHOTO 2: WELL SIGN**

## Inspection Photos

Location Name: LORENCITO 1-14-34-67

API#: 05-071-07719

INSP. #: 695101001



**PHOTO 3: TRASH IN PIT. REMOVE TRASH IN ACCORDANCE WITH RULE 603.f. CA DATE 8/9/19**

**PHOTO 4: NO 2' FREEBOARD MARKER IN PIT. INSTALL 2' FREEBOARD MARKER IN ACCORDANCE WITH RULE 902.b. CA DATE 8/9/19**

## Inspection Photos

Location Name: LORENCITO 1-14-34-67

API#: 05-071-07719

INSP. #: 695101001



**PHOTO 5: UNUSED EQUIPMENT (2" RISER NEAR WELLHEAD).  
REMOVE UNUSED RISER IN ACCORDANCE WITH NTO AND  
WITH RULE 603.f. CA DATE 10/9/19**

