

Inspection Photos
Location Name: McCallum Unit 106
Location ID: 324665

FORM 21
State of Colorado
Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

Well Information:
 Well Name: Pierre "B"
 Wellbore ID: 1076-1100
 Operator: McCallum Unit 106
 Location: McCallum Unit 106

Test Type:
☒ **SHUT-IN PRODUCTION WELL**
☐ **INJECTION WELL**

Casing Test Results:
 Test Date: 7/9/19
 Test Time: 12:25
 Test Results: Pass
 Test Type: PS
 Test Results: Pass
 Test Type: PS
 Test Results: Pass

Signatures:
 Production Supervisor: [Signature] Date: 7-9-19
 Field Inspector: [Signature] Date: 7/9/19

Inspection Document # 689803896

Photo 1. Photo of Form 21 as filled out and signed in the field.