

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/10/2019

Document Number:

689802889**FIELD INSPECTION FORM**
 Loc ID 313204 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 56565Name of Operator: MERIT ENERGY COMPANYAddress: 13727 NOEL ROAD STE 1200City: DALLAS State: TX Zip: 75240**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hindle, Holly		holly@northshoreenergyllc.com	
Valliquette, Arlene		Arlene.Valliquette@meritenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273275	WELL	TA	11/01/2018	GW	081-07197	FEDERAL 43-20	SI

**General Comment:**[COGCC Inspection Report 689802889 Summary](#)

On Monday 7/8/2019 at approximately 12:00, I, Inspector Emily Waldron, conducted a field inspection at Merit Energy/North Shore Exploration and Production LLC Federal 43-20, at 081-07197 in Moffat County Colorado.

While there, I observed a MIT in response to warning letter document number 401966199.

During this inspection the following possible compliance issues were observed:

Test was charted in the field using a 10,000 psi chart, all gauges available on location were 5,000 psi or higher, well was tested to 400 psi. Form 10 document number 401864556, submitted 2/14/2019, On Hold to transfer from Merit Energy Company to North Shore Exploration and Production LLC.

This is a summary of inspection report 689802889.

**Inspected Facilities**Facility ID: 273275 Type: WELL API Number: 081-07197 Status: TA Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Inspector on location to witness MIT being performed in response to warning letter document number 401966199. Test was charted in the field using a 10,000 psi chart, all gauges available on location were 5,000 psi or higher, well was tested to 400 psi. Casing appeared to hold 400 psi for 15 minutes and test was passed in the field.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802901	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874020">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874020</a>