

Inspection Photos
Operator: Kinder Morgan
Location/API #: 033-06183
Date: 7-1-2019



Photo 1. View of the eastern edge project area from the southwestern corner facing northward. Compacted berm in place around perimeter of disturbance areas. Topsoil stockpiled within.



Photo 2. View of the well pad construction from the southeastern corner facing center. Well location staked.



Photo 3. View of the northern edge of the project area. Compacted berm in place. Topsoil stored in northern project area.



Photo 4. View of rock check along access road and compacted berm in place.