

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

697600257**FIELD INSPECTION FORM**
 Loc ID 420044 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420041	WELL	SI	02/01/2019	GW	123-32436	FIVE RIVERS K 08-24D	EI
420046	WELL	SI	02/01/2019	GW	123-32439	FIVE RIVERS K 08-23	EI
420052	WELL	PR	08/01/2018	GW	123-32441	FIVE RIVERS K 09-33D	EI
420053	WELL	PR	04/21/2011	GW	123-32442	FIVE RIVERS K 16-30D	EI

General Comment:[production facilities not co-located with well and battery not inspected in this report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 420041	Type: WELL	API Number: 123-32436	Status: SI	Insp. Status: EI
Facility ID: 420046	Type: WELL	API Number: 123-32439	Status: SI	Insp. Status: EI
Facility ID: 420052	Type: WELL	API Number: 123-32441	Status: PR	Insp. Status: EI
Facility ID: 420053	Type: WELL	API Number: 123-32442	Status: PR	Insp. Status: EI

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: no means of production at wellhead
sign indicates TA for prep before nearby horizontal drilling
valves on wellhead are in lockout tagout mode

Corrective Action: _____ Date: _____