

Inspection Photos

07/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313784

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313784



Photo 1: Photo taken from the northwest end of the location, facing southeast. Photo shows overview of the location.



Photo 2: Photo taken from the northwest end of the location, facing south. Photo shows overview of the location.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313784



Photo 3: Photo taken from the north end of the location, facing east. Photo shows location remains predominantly bare and exposed soil, or undesirable weedy plant species. Unable to find evidence that additional reclamation activities have been conducted.



Photo 4: Photo taken from the well location. Facing northeast. Photo shows area where the concrete pump base was removed. Location remains predominantly bare and exposed soil, or undesirable weedy plant species. Unable to find evidence that additional reclamation activities have been conducted. Operator appears to have only removed base and backfilled.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313784



Photo 5: Photo taken from the south end of the location, facing northeast. See comments under photo 3.



Photo 6: Photo taken from the south end of the location, facing north. See comments under photo 3.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313784



Photo 7: Photo taken from the location, facing south. Photo shows access road has not been reclaimed.



Photo 8: Photo shows access road has not been reclaimed.