

Inspection Photos
Location Name: Marie Gerhardt B #6
Location ID: 318334



Photo 1 WH and WH sign not legible.



Photo 2 Unused equipment: PU base and gear box with weights.



Inspection Photos
Location Name: Marie Gerhardt B #6
Location ID: 318334



Photo 3 Unused equipment: Walking beam, pitman arms, horses head and cattle panels.



Photo 4 Unused equipment: Electric panel and breaker box, meter has been removed.