

Laramie Energy LLC
API # 05-077-09272
Inspection # 696600293



Photo #1. Photo at entrance of location.

Photo #2 Photo at entrance of location.

Laramie Energy LLC
API # 05-077-09272
Inspection # 696600293



Photo #3. Photo of tank battery.

Photo #4. Photo of Wellheads

Laramie Energy LLC
API # 05-077-09272
Inspection # 696600293



Photo #5. Photo of wellhead signs missing or laying on the ground

Photo #6. Photo of unused equipment on location by wellheads

Laramie Energy LLC
API # 05-077-09272
Inspection # 696600293



Photo #7. Photo of unused equipment on location by wellheads



Photo #8. Photo of unused equipment on location by wellheads