

Inspection Photos

API: 05-071-07927

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/11/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019

Inspection Photos



Photo 1. Facing west toward the recontoured location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019

Inspection Photos



Photo 2. Facing west toward the recontoured location. Vegetation is beginning to establish in areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019

Inspection Photos



Photo 3. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019

Inspection Photos



Photo 4. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019

Inspection Photos



Photo 5. Rock rip/rap is installed at the lower part of the location for outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019

Inspection Photos



Photo 6. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07927 | Date: 7/11/2019