

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2019

Submitted Date:

07/12/2019

Document Number:

680305244

**FIELD INSPECTION FORM**

Loc ID 313691 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10657  
Name of Operator: PCR OPERATING LLC  
Address: 4040 BROADWAY STREET #510  
City: SAN ANTONIO State: TX Zip: 78209

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wehrer, Gene	(970) 380-4860	gwehrer@passcreekresource.com	<a href="#">Adena Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224867	WELL	SI	12/06/2018	ERIW	087-05259	Clar B-1	SI

**General Comment:**

[Routine Site Inspection FIR - Satisfactory](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track grassland		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	# 0		corrective date
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 224867 Type: WELL API Number: 087-05259 Status: SI Insp. Status: SI

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Site Inspection FIR - Satisfactory</a>	schureky	07/12/2019