

Caerus Piceance LLC
API # 05-077-09239
Inspection # 696600299



**Photo #1. Photo at entrance of location.
Battery sign posted at entrance or at Wellhead, both missing
information.**

Photo #2 Photo at entrance of location.

Caerus Piceance LLC
API # 05-077-09239
Inspection # 696600299



Photo #3. Photo of Stored pipe or unused equipment on location.



Photo #4. Photo of Wellhead.
missing information

Caerus Piceance LLC
API # 05-077-09239
Inspection # 696600299



Photo #5 Photo of location from entrance



Photo #6 Photo of location from entrance