

Caerus Piceance LLC
API # 05-077-08947
Inspection # 696600301



Photo #1. Photo at entrance of location.
Battery sign posted at entrance missing information.
Weeds surrounding sign



Photo #2 Photo at entrance of location.
Battery sign posted at entrance missing information.
Weeds surrounding sign

Caerus Piceance LLC
API # 05-077-08947
Inspection # 696600301



Photo #3. Photo of location at entrance.



Photo #4. Photo Tank Battery

Caerus Piceance LLC
API # 05-077-08947
Inspection # 696600301



Photo #5 Photo of Trash in containment



Photo #6 Photo of Weeds growing in containment

Caerus Piceance LLC
API # 05-077-08947
Inspection # 696600301



Photo #7 Wellheads on location



Photo #8 Photo of Separators

Caerus Piceance LLC
API # 05-077-08947
Inspection # 696600301



Photo#7 Trash on location. (More under shade of man hole covers)



Photo#8 Trash and unused equipment stored in tank containment

Caerus Piceance LLC
API # 05-077-08947
Inspection # 696600301



Photo #9 Stored unused equipment on location.