Inspection Photos
Location Name: 35-7-8-1 (SFTC #1)
API: 05-067-08801

South Fork Texas Creek monitoring well location photo.

Metal shack housing telemetry and ancillary equipment. SFTC methane mitigation system in the background.

Inspection Photos
Location Name: 35-7-8-1 (SFTC #1)
API: 05-067-08801

Protective cage removed from well #1 for repairs.

120 psi on pressure gauge prior to bleeding well down.

Inspection Photos
Location Name: 35-7-8-1 (SFTC #1)
API: 05-067-08801

Wellhead shut in after replacing rugged cable and lower transducer.

Protective cage replaced after replacing down hole transducer and cable.