

Inspection Photos
Location Name: MOUNTAIN LION 11-18
API#: 05-071-06575
INSP. #: 695101009



Colorado Oil & Gas Conservation Commission
37.08961, -104.72006, 2160.0m, 215°
2019/07/12 09:33:59

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.08967, -104.7202, 2157.0m, 231°
2019/07/12 09:34:13

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: MOUNTAIN LION 11-18

API#: 05-071-06575

INSP. #: 695101009



PHOTO 3: AREA OF EROSION ON WEST SIDE OF ROW NORTH OF LOCATION TOWARD THE BOTTOM OF THE HILL. REPAIR EROSION AND REPAIR OR INSTALL BMP'S TO PREVENT EROSION AND COMPLY WITH RULE 1002.f. CA DATE 8/12/19

PHOTO 4: AREA OF EROSION ON EAST SIDE OF ROW NORTH OF LOCATION TOWARD THE BOTTOM OF THE HILL. REPAIR EROSION AND REPAIR OR INSTALL BMP'S TO PREVENT EROSION AND COMPLY WITH RULE 1002.f. CA DATE 8/12/19

Inspection Photos

Location Name: MOUNTAIN LION 11-18

API#: 05-071-06575

INSP. #: 695101009



PHOTO 3: AREA OF EROSION ON EAST SIDE OF ROW APP. 200 YARDS NORTH OF LOCATION. REPAIR EROSION AND REPAIR OR INSTALL BMP'S TO PREVENT EROSION AND COMPLY WITH RULE 1002.f. CA DATE 8/12/19