



7/14/19

Looking north across storage yard at Haswell  
Field





7/14/19 Looking west across storage yard at Haswell  
Field





7/14/19 looking SW across storage yard Haswell Field





7/14/19

Looking south across storage yard to Grace 2-6  
production equipment





7/14/19 looking SE across storage yard. Trance 1-6 on the left, Trance 2-6 on right side, contractor equipment used in clean up in center





7/14/19 looking SE across storage yard past contractor equipment used for cleanup to the Frazee 1-6 well in distance





7/14/19 Looking SSE across storage yard.  
Frazee 2-6 on right side with production equipment  
Contractor equipment used to remove storage items on  
left side of picture





7/14/9 looking NNE across storage yard  
Haswell field





7/14/19 looking Northeast across storage yard past production  
equipment Haswell Field





7/14/19 Looking east across storage yard past production Equip  
Haswell Field