



7/14/19

looking SW on lease road, Haswell Field.  
Crowned, ditched and rocked





7/14/19

looking north on lease road to Ranch Horse  
Hassell field. Crowned, ditched and rocked





7/14/19

looking south on lease road. Road crowned,  
ditched and rocked





7/17/19

looking NW past Frazee 2-6 production equipment  
on left, pipeline equipment on right.  
Road crowned + ditched