

Construction and Stormwater Inspection

July 10, 2019

Operator: PETROSHARE CORPORATION- #10454

Location ID: 451646

Inspection Document #: 697500316

Adams County, CO

SESW Section 20 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 1. Photo taken from the southern Location, facing East. Photo illustrates Operator was in-process of installing the perimeter BMP (ditch and berm) at the time of my inspection.



Photo 2. Photo taken from the southeastern perimeter of Location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 3. Photo taken from the northeastern Location, facing West. See comments under Photo 1.



Photo 4. Photo taken from the northwestern perimeter of Location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 5. Photo taken from the entrance of Location, facing East. Photo illustrates the berm BMP has been temporarily stabilized with equipment tracking.