

Final Reclamation Inspection

July 10, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

API#: 05-001-06809

Inspection Document #: 697500318

Adams County, CO

NESW Section 20 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DAVIS #1
API# 05-001-06809



Photo 1. Photo taken from the PA well location, facing West. No visual evidence of oil and gas equipment at the well location. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of reference crop areas.



Photo 2. Photo taken from the PA well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: DAVIS #1
API# 05-001-06809



Photo 3. Photo taken from the PA well location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the PA well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: DAVIS #1
API# 05-001-06809



Photo 5. Reference photo taken southeast from the PA well location, facing West.
See comments under Photo 1.