

Inspection Photos
Location Name: Coulson Tank Battery
Facility ID: 425972



Tank battery



Inspection Photos
Location Name: Coulson Tank Battery
Facility ID: 425972



Condensate tank placards on 3/6/19



Condensate tank placards on 7/17/19

Inspection Photos
Location Name: Coulson Tank Battery
Facility ID: 425972



Colorado Oil & Gas Conservation Commission
40.33773, -104.86214, 1432.0m, 84°
03/06/2019 10:13:14 AM

Condensate tank placards on 3/6/19



Colorado Oil & Gas Conservation Commission
40.33774, -104.86214, 1429.0m, 78°
07/15/2019 01:26:29 PM

Condensate tank placards on 7/17/19