

Inspection Photos
Location Name: Fritzler Battery
Location ID: 422262



Photo 1: Location



Photo 2: Tank Battery

Inspection Photos
Location Name: Fritzler Battery
Location ID: 422262



Photo 3: Labeling Faded on crude oil tank.



Photo 4: Labeling faded on crude oil tank.

Inspection Photos
Location Name: Fritzier Battery
Location ID: 422262



Photo 5: Bucket of unknown contents in north separator house.



Photo 6: Separator with unknown substance in housing.

Inspection Photos
Location Name: Fritzler Battery
Location ID: 422262



Photo 7: Unused riser; unused equipment