

Inspection Photos
Location Name: Vaneta 1-32D
Location ID: 324752



Photo 1. Overflowing stock tank with oily waste inside berm, oily waste in berm.



Photo 2. Oily waste in berm.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Vaneta 1-32D
Location ID: 324752



Photo 3. Example of debris on location perimeter.



Photo 4. Example of debris migrating off location.



Inspection Photos
Location Name: Vaneta 1-32D
Location ID: 324752



Photo 5. Example of stained soil/gravel on location.



Photo 6. Example of stained soil/gravel on location.

