



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jun 20, 2019 7:31:24 AM MDT
Server Receive Date:	Jun 20, 2019 7:33:00 AM MDT
Reference Number:	20190620-18109581609
Location:	557 Airpark Dr, Durango, CO 81303, USA Jun 20, 2019 7:31:14 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jun 17, 2019
Well Name	JONES GAS UNIT 34-16 1
API Number	50670769400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Photo of first corrective action completed



Completed work description Corrective Action 1

Sprayed Canada Thistle populations.

Photo of second corrective action completed



Completed work description of corrective action 2

Sprayed muskthistle.

Photo of third corrective action completed



Completed work description of corrective action 3

Sprayed Canada Thistle populations.

Photo of fourth corrective action completed



Completed work description of corrective action 4

Sprayed musk thistle populations.

Additional photos



Additional photos



Completed work description

Sprayed Musk and Canada thistle populations in the project area.

Summary of all work completed

Selectively treated thistle populations in reclamation area.