

Inspection Photos  
Location Name: Haller 42-11-1  
Location ID: 318227



**Pic 1 unused equipment**



**Pic 2 stained soil/possible leak by wellhead**

**Inspection Photos**  
**Location Name: Haller 42-11-1**  
**Location ID: 318227**



**Pic 3 stained soil under pumping unit**