

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2019

Submitted Date:

07/16/2019

Document Number:

693500827**FIELD INSPECTION FORM**

Loc ID 319426 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | COGCCinspections@anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------------|-------------|
| 243451      | WELL | SI     | 03/01/2019  | GW         | 123-11242 | MARTIN T. HART GAS<br>UNIT E TRUE 1 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |               |       |  |
|--------------------|---------------|-------|--|
| <b>Fencing/:</b>   |               |       |  |
| Type               | WELLHEAD      |       |  |
| Comment:           | Steel rod     |       |  |
| Corrective Action: |               | Date: |  |
| Type               | SEPARATOR     |       |  |
| Comment:           | Square tubing |       |  |
| Corrective Action: |               | Date: |  |
| Type               | TANK BATTERY  |       |  |
| Comment:           | barb wire     |       |  |
| Corrective Action: |               | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bradenhead                  | # 1 |       |                 |

|   |     |       |
|---|-----|-------|
| Comment: <a href="#">Appears to be plumbed to surface</a> |     | Date: |
| Corrective Action:  |     | Date: |
| Type: Gas Meter Run                                       | # 1 |       |
| Comment:  |     | Date: |
| Corrective Action:  |     | Date: |
| Type: Plunger Lift  | # 1 |       |
| Comment:  |     | Date: |
| Corrective Action:  |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   | Date:    |           |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLS | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   | Date:    |                |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
|   |          |                     |                     |             |
| Comment: <a href="#">Shares containment with crude oil tank</a> |          |                     |                     |             |
| Corrective Action:  |          | Date:               |                     |             |

**Venting:**

|        |    |
|--------|----|
| Yes/No | NO |
|--------|----|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 243451 | Type: | WELL | API Number: | 123-11242 | Status: | SI | Insp. Status: | SI |
| Idle Well  |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |       |      |             |           |         |    |               |    |
| Comment: <input type="text" value="SI. Well head has sing stated shut in for HZ prep."/>                                 |        |       |      |             |           |         |    |               |    |
| Corrective Action: <input type="text"/> Date: _____  |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment                            | User    | Date       |
|------------------------------------|---------|------------|
| <a href="#">Routine inspection</a> | silverr | 07/16/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 693500828    | loc pic     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880791">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880791</a> |