

Inspection Photos

Loc#414127

Operator: Sandridge

Inspection Number: 692401146

Inspection Date: 6/27/19





Photo#1:
Overviews of Location from entry to West.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Hebron Location #414127



Photo#2:
White top and Canada thistle, Noxious Weeds established on site.



Photo#3:
White top and Canada thistle, Noxious Weeds established on site.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Hebron Location #414127



Photo#4:
Material piles on site, have trash/debris mixed with material. No BMPs employed on stockpiles.



Photo#5:
Ponding, rutting site degradation occurring at Southeast end of site.

June 27, 2019



Photo#6:
Debris weeds on site perimeters.



Photo#7:
Debris weeds on site perimeters.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Hebron Location #414127



Photo#8:
Growth of native wildflower, Penstemon on site
perimeters.



Photo#9:
Growth of native wildflower, Penstemon on site.

June 27, 2019