

Inspection Photos

Location Name: ROAD RUNNER 12-7

API#: 05-071-06573

INSP. #: 695101044



PHOTO 1: WELLHEAD/ UNUSED EQUIPMENT ON LOCATION. FENCING AND GUARDS NOT INSTALLED AND ARE JUST LEANING AGAINST WELLHEAD. **INSTALL FENCING AND GUARDS CORRECTLY. CA DATE 8/16/19**

PHOTO 2: WELL SIGN