

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402108590

Receive Date:

07/16/2019

Report taken by:

PETER GINTAUTAS

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers
Address: <u>1775 SHERMAN STREET - STE 3000</u>		Phone: <u>(303) 860-5800</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>
Contact Person: <u>Karen Olson</u>	Email: <u>COGCCSpillRemediation@pdce.com</u>	Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 12692 Initial Form 27 Document #: 401962147

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>336537</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>WARNER W-62N66W 14NWNE</u>		Latitude: <u>40.143800</u>	Longitude: <u>-104.741860</u>
		** correct Lat/Long if needed: Latitude: <u>40.141678</u>	Longitude: <u>-104.740356</u>
QtrQtr: <u>NWNE</u>	Sec: <u>14</u>	Twp: <u>2N</u>	Range: <u>66W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

The following additional receptors were evaluated and determined to be outside of the 1/4-mile radius of the site: occupied building, CPW Sensitive Wildlife Habitat (SWH), and FWS wetlands.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	TBD	Confirmation soil sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In accordance with COGCC Rule 905.b, confirmation samples will be collected below the buried or partially buried produced water vessel during decommissioning or relocation activities.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil encountered below the produced water vessel will be field screened for volatile organic compound (VOC) concentrations using a photoionization detector (PID). In addition, visual and olfactory observations of the soil will be documented. A confirmation soil sample will be collected below the vessel and submitted for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) – gasoline range organics (GRO) by EPA Method 8260B, TPH – diesel range organics (DRO) by EPA Method 8015, pH by EPA Method 9045, and electrical conductivity (EC) by Standard Method (SM) 2510B.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered below the vessel, a groundwater sample will be collected and submitted for laboratory analysis of BTEX by EPA Method 8260B.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 61

Number of soil samples exceeding 910-1 6

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 18375

NA / ND

-- Highest concentration of TPH (mg/kg) 890

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 18

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 10'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☒ Were impacts to adjacent property or offsite impacts identified?

Excavation activities were conducted off-site to the east of the facility. Soil samples collected from the final excavation extent indicated that hydrocarbon impacted material was successfully removed.

☐ Were background samples collected as part of this site investigation?

☒ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 6410

Volume of liquid waste (barrels) 73

☒ Is further site investigation required?

Groundwater was encountered in the excavation at approximately 10 feet below ground surface (bgs). However, a groundwater sample could not be collected due to slow and discontinuous aquifer recharge. Therefore, a supplemental groundwater assessment will be conducted within and surrounding the former excavation extent.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

On April 24, 2019, confirmation soil sampling was conducted during the removal of the produced water vessel. During facility decommissioning activities, a historic release was discovered below the production lines. Between April 24 and June 5, 2019, approximately 6,410 cubic yards of impacted material were removed and transported to the Buffalo Ridge Landfill for disposal under PDC waste manifests. Soil samples collected from the final extent of the excavation indicated that hydrocarbon impacted material was successfully removed.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

On April 24, 2019, confirmation soil samples were collected below the former vessel and submitted for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) – gasoline range organics by EPA Method 8260B, TPH – diesel range organics (DRO) by EPA Method 8015, pH by EPA Method 9045 and electrical conductivity (EC) by SM 2510B. Soil sample locations are illustrated on Figure 1 and analytical results are summarized in Table 1. In addition, a historic release was discovered below the production lines during facility decommissioning activities. Soil samples were collected from the sidewalls and base of the excavation at depths ranging between 7 feet and 18.5 feet below ground surface (bgs). Soil samples were submitted for laboratory analysis of BTEX, naphthalene, TPH – GRO by EPA Method 8260B, and TPH – DRO by EPA Method 8015. The excavation extent and soil sample locations are illustrated on Figure 1. Analytical results are summarized in Table 2. Groundwater was encountered in the excavation at approximately 10 feet bgs, however a groundwater sample could not be collected due to slow and discontinuous aquifer recharge. Therefore, a supplemental groundwater assessment will be conducted within and surrounding the former excavation extent.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal
If Yes: Estimated Volume (Cubic Yards) _____ 6410
Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
☐ _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was encountered in the excavation at approximately 10 feet bgs, however a groundwater sample could not be collected due to slow and discontinuous aquifer recharge. Therefore, a supplemental groundwater assessment will be conducted within and surrounding the former excavation extent. Proposed monitoring well locations are illustrated on Figure 2.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial reuse.

Volume of E&P Waste (solid) in cubic yards 6410

E&P waste (solid) description E&P Contaminated Soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Buffalo Ridge Landfill

Volume of E&P Waste (liquid) in barrels 73

E&P waste (liquid) description E&P Contaminated Groundwater

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: NGL Energy Facility

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

Do all soils meet Table 910-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The facility was decommissioned. The location will be reclaimed in accordance with COGCC 1000 Series rules.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/18/2019

Date of commencement of Site Investigation. 04/24/2019

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. 04/24/2019

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Karen Olson

Title: Snr Program Manager

Submit Date: 07/16/2019

Email: COGCCSpillRemediation@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 07/17/2019

Remediation Project Number: 12692

COA Type

Description

	Submit reports of site investigation and progress of remediation including results of sampling and analysis on a quarterly basis or more often until remediation is closed.
	Add results of PID screening to analytical results table and submit revised analytical results table with next supplemental form 27

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

402108590	FORM 27-SUPPLEMENTAL-SUBMITTED
402108685	SOIL SAMPLE LOCATION MAP
402108687	SITE INVESTIGATION PLAN
402108690	ANALYTICAL RESULTS

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)