

Inspection Photos

Loc#451937

Operator: Sandridge

Inspection Number: 692401149

Inspection Date: 6/27/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast. Insert is view South of expansion area.

June 27, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Shiras CTB Loc#451937



Photo#2:
Debris collected in corner and along fence.



Photo#3:
Waste material pile in Northeast corner of site

June 27, 2019



Photo#4:
View from East end of expansion area back to main Location.



Photo#5:
Sediment reservoir & sediment moving off site.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Shiras CTB Loc#451937



Photo#6:
Erosion occurring as stormwater enters sediment reservoir.



Photo#7:
Washout point in reservoir berm

June 27, 2019