

Inspection Photos
Location Name: LDS F-66N65W /36SWSW
Location #: 302782



Photo #1

LDS F 01-29 (API # 05-123-29793) Wellsite

Shut-In | SI

Emergency contact number NOT Legible

prior insp.



Photo #2

LDS F 01-29 Wellsite

Shut-In | SI

Emergency contact number NOW Legible

Inspection Photos
Location Name: LDS F-66N65W /36SWSW
Location #: 302782



Colorado Oil & Gas Conservation Commission
40.43519, -104.61144, 1391.0m, 329°
05/31/2019 03:04:18 PM

Photo #3

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down

*Mud w/ puddles from prior rain
prior insp.*



Colorado Oil & Gas Conservation Commission
40.43533, -104.61203, 1402.0m, 38°
07/16/2019 03:25:27 PM

Photo #4

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down