

Inspection Photos
Operator: BP America
Location/API #: 067-09503
Date: 7-10-2019



Photo 1. View of the southern project area from the southeastern corner facing westward.



Photo 2. View of musk thistles within the interim reclamation area.