

Location:	#2 Ann Walker
Line:	Fuel Supply Line
Technicians:	Bill Espinosa
Date	6/14/2019
Time	Pressure (PSI)
1:00:20 PM	1.3
1:00:50 PM	1.3
1:01:20 PM	1.2
1:01:50 PM	4.9
1:02:20 PM	5.7
1:02:50 PM	5.7
1:03:20 PM	5.7
1:03:50 PM	5.7
1:04:20 PM	5.7
1:04:50 PM	5.7
1:05:20 PM	34.4
1:05:50 PM	34.3
1:06:20 PM	34.1
1:06:50 PM	33.9
1:07:20 PM	33.8
1:07:50 PM	33.6
1:08:20 PM	33.4
1:08:50 PM	33.3
1:09:20 PM	33.2
1:09:50 PM	33
1:10:20 PM	32.9
1:10:50 PM	32.7
1:11:20 PM	32.6
1:11:50 PM	32.4
1:12:20 PM	32.3
1:12:50 PM	32.1
1:13:20 PM	31.9
1:13:50 PM	31.8
1:14:20 PM	31.7
1:14:50 PM	31.6
1:15:20 PM	31.4
1:15:50 PM	31.3
1:16:20 PM	31.1
1:16:50 PM	31
1:17:20 PM	30.8
1:17:50 PM	30.7
1:18:20 PM	30.6
1:18:50 PM	30.4
1:19:20 PM	30.3
1:19:50 PM	30.2
1:20:20 PM	30
1:20:50 PM	29.9

1:21:20 PM	29.7
1:21:50 PM	29.6
1:22:20 PM	29.6
1:22:50 PM	29
1:23:20 PM	29.4
1:23:50 PM	29.4
1:24:20 PM	29.3
1:24:50 PM	29.3
1:25:20 PM	29.3
1:25:50 PM	29.1
1:26:20 PM	29.1
1:26:50 PM	29
1:27:20 PM	29
1:27:50 PM	29
1:28:20 PM	29
1:28:50 PM	29
1:29:20 PM	29
1:29:50 PM	29
1:30:20 PM	29
1:30:50 PM	29
1:31:20 PM	29
1:31:50 PM	29
1:32:20 PM	29
1:32:50 PM	29
1:33:20 PM	29.3
1:33:50 PM	29.2
1:34:20 PM	29
1:34:50 PM	29
1:35:20 PM	29
1:35:50 PM	29
1:36:20 PM	29
1:36:50 PM	28.9
1:37:20 PM	28.9
1:37:50 PM	28.9
1:38:20 PM	28.9
1:38:50 PM	28.9
1:39:20 PM	28.9
1:39:50 PM	28.9
1:40:20 PM	28.9
1:40:50 PM	28.9
1:41:20 PM	28.9
1:41:50 PM	28.9
1:42:20 PM	28.9
1:42:50 PM	28.9
1:43:20 PM	28.9
1:43:50 PM	28.8
1:44:20 PM	28.8

1:44:50 PM	28.8
1:45:20 PM	10
1:45:50 PM	1.3
1:46:20 PM	1.3
1:46:50 PM	1.2
1:47:20 PM	1.4
1:47:50 PM	1.8
1:48:20 PM	1.8
1:48:50 PM	1.8
1:49:20 PM	1.7
1:49:50 PM	1.7
1:50:20 PM	1.7

Pass/Fail

% loss over 30 minutes	8.28%	Less than 10%	Yes		
% loss in last 5 minutes	0.35%	Less than 1%	Yes		Pass

