

# Inspection Photos

API: 05-071-06169

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/15/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-06169 | Date: 7/15/2019

## Inspection Photos



**Photo 1.** There are vehicle ruts and potholes on the main road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06169 | Date: 7/15/2019

## Inspection Photos



**Photo 2.** There is a water leak occurring at the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06169 | Date: 7/15/2019

## Inspection Photos



**Photo 3.** There is oil in the engine skid and staining.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06169 | Date: 7/15/2019