

Inspection Photos

API: 05-071-07943

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/15/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07943 | Date: 7/15/2019

Inspection Photos



Photo 1. There are vehicle ruts which creates a conveyance for stormwater erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07943 | Date: 7/15/2019

Inspection Photos



Photo 2. There is a water leak occurring at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07943 | Date: 7/15/2019

Inspection Photos



Photo 3. There is oil in the engine skid and staining.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07943 | Date: 7/15/2019