

Inspection Photos  
Location Name: Hankins Location  
Location ID: 317495



Photo 1: Wellhead; equipment removed.



Photo 2: BBLS on sign to produced water tank

