

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402108982
Receive Date:
07/15/2019

Report taken by:
Candice (Nikki) Graber

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATON

Name of Operator: SRC ENERGY INC	Operator No: 10311	Phone Numbers
Address: 1675 BROADWAY SUITE 2600		Phone: (970) 4755220
City: DENVER State: CO Zip: 80202		Mobile: ()
Contact Person: Dave Castro	Email: dcastro@srcenergy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION
Remediation Project #: 13062 Initial Form 27 Document #: 401993810

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other

SITE INFORMATION N Multiple Facilites (in accordance with Rule 909.c.)

Facility Type: LOCATION	Facility ID: 326979	API #:	County Name: WELD
Facility Name: MOSSBERG PMJ-65N66W 30NWSE	Latitude: 40.368534	Longitude: -104.819473	
	** correct Lat/Long if needed: Latitude: 40.367974	Longitude: -104.818169	
QtrQtr: NWSE	Sec: 30	Twp: 5N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use crop land

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	TBD	sampling
Yes	SOILS	25' x 40'	sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The partially buried produced water vault was removed. Initial pit soil sampling results came back over Table 910-1 limits. A soil and groundwater impact investigation was done, which included removing approximately 400 yards of impacted soil. Groundwater was encountered during excavation at 15' below ground surface, which was also sampled. Those results also came back over Table 910-1 limits. Excavation soil samples confirm all of the impacted soil above the saturated zone has been removed. Approximately 35 bbls of impacted groundwater were removed by a hydrovac truck, followed by the application of 220 lbs of carbon amendment to the exposed excavation bottom. The excavation was then been backfilled.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

The proposed monitoring wells will have well bore soil samples field screened and analyzed for BTEX, DRO, and GRO, since they will be outside of the backfilled excavation. Soil samples will be sent to Origins Laboratory in Denver for analysis.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

SRC and Tasman propose 6 monitoring wells as shown on the attached figure to being the groundwater impact extent investigation. Once installed and developed, the wells will be sampled and analyzed for BTEX at Origins Laboratory in Denver.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Additional monitoring wells may be installed if groundwater impact extents are not defined after the first 6 MWs are installed and sampled.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 1000

NA / ND

-- Highest concentration of TPH (mg/kg) 3565

-- Highest concentration of SAR 1

BTEX > 910-1 Yes

Vertical Extent > 910-1 (in feet) 14

Groundwater

Number of groundwater samples collected 1

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 15

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 1

-- Highest concentration of Benzene (µg/l) 1560

-- Highest concentration of Toluene (µg/l) 128

-- Highest concentration of Ethylbenzene (µg/l) 270

-- Highest concentration of Xylene (µg/l) 2320

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 400

Volume of liquid waste (barrels) 35

Is further site investigation required?

SRC and Tasman proposed to start with the 6 monitoring wells on the attached map to begin groundwater impact extent investigation. More monitoring wells may need to be installed to define impact extents.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Partially buried produced water vault was removed by Unlimited.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

The partially buried produced water vault was removed. Initial pit soil sampling results came back over Table 910-1 limits. A soil and groundwater impact investigation was done, which included removing approximately 400 yards of impacted soil. Groundwater was encountered during excavation at 15' below ground surface, which was also sampled. Those results also came back over Table 910-1 limits. Excavation soil samples confirm all of the impacted soil above the saturated zone has been removed. Approximately 35 bbls of impacted groundwater were removed by a hydrovac truck, followed by the application of 220 lbs of carbon amendment to the exposed excavation bottom. The excavation was then been backfilled.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____ 400

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Once groundwater impact extents have been defined, quarterly monitoring for BTEX until 4 consecutive quarters of Table 910-1 compliance has been achieved.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other _____
Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

non- produced water impacted soil and groundwater

Volume of E&P Waste (solid) in cubic yards 400

E&P waste (solid) description impacted soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: North Weld Landfill

Volume of E&P Waste (liquid) in barrels 35

E&P waste (liquid) description impacted groudwater

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: CSI Bennett

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

Do all soils meet Table 910-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will occur, per COGCC rules, once all MW necessary for impact extent definition have been installed.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/02/2019

Date of commencement of Site Investigation. 06/12/2019

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

This SF27 is to provide update on investigation and remediation activities to-date. SRC and Tasman propose 6 MWs to be installed to begin the groundwater impact extent investigation. All figures, and lab analytical reports are attached.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Dave Castro

Title: Sr. Env. Specialist

Submit Date: 07/15/2019

Email: dcastro@srcenergy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Candice (Nikki) Graber

Date: 07/17/2019

Remediation Project Number: 13062

COA Type**Description**

	<p>The following conditions of approval apply to this workplan:</p> <ul style="list-style-type: none"> - Operator shall notify COGCC EPS personnel no less than 72 hours prior to installing proposed monitoring wells. Operator shall provide boring logs in accordance with standard environmental practices. This includes at a minimum; lithology description, USCS classifications, PID readings, sample collection depths, depth to water, and well construction. - Operator shall submit a supplemental Form 27 no less than 45 days after the completion of monitoring well installation and groundwater sampling. At that time, if point of compliance has been established, Operator may begin annual reporting. - On the next Form 27 Supplemental Report, specify the amount (volume or mass) and name brand of groundwater amendment added to the excavation. Attach the SDS for any additives applied to the excavation or injected at the site.
--	---

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402108982	FORM 27-SUPPLEMENTAL-SUBMITTED
402109153	ANALYTICAL RESULTS
402109162	SITE MAP
402109172	ANALYTICAL RESULTS
402109182	CORRESPONDENCE

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)