

Inspection Photos
Operator: BP America
Location/API #: 067-08720
Date: 7-11-2019



Photo 1. View of what appears to be topsoil stockpile within the southwestern project area. This soil stockpile is not stabilized as it is largely vegetated with annual weeds such as cheatgrass (*Bromus tectorum*) and Scotch thistle (*Onopordum acanthium*).



Photo 2. View of Scotch thistle infestation within the southern project area.



Photo 3. View of revegetation within the western project area from the southwestern edge facing northward.