

Inspection Photos
Operator: BP America
Location/API #: 067-06944
Date: 7-11-2019



Photo 1. View of eastern project area from the southeastern corner facing northward.



Photo 2. View of the southern project area from the southeastern corner facing westward.



Photo 3. View of black plastic netting debris that remains within the project area after 2017 corrective action.