

TEP  
API # 05-045-18850  
Inspection # 696600338



Photo #1 Photo of Battery sign at access road entrance.



Photo #2 Photo at access road entrance.  
Battery sign not apparent to tank battery.

TEP  
API # 05-045-18850  
Inspection # 696600338



**Photo # 3 Photo at entrance to location**



TEP  
API # 05-045-18850  
Inspection # 696600338




Photo #4 Photo of tank battery



Photo #5 Photo of wellhead



TEP  
API # 05-045-18850  
Inspection # 696600338



**Photo # 6 Riser at Separator needs marked and Locked out tagged out and removed to complete PA status**



**Photo # 7 Riser at Separator needs marked and Locked out tagged out and removed to complete PA status**

TEP  
API # 05-045-18850  
Inspection # 696600338



**Photo # 8 Holes in tank containment liner**



**Photo # 9 Holes in tank containment liner**



TEP  
API # 05-045-18850  
Inspection # 696600338



**Photo # 10 Holes in tank containment liner**



**Photo # 11 Holes in tank containment liner**

TEP  
API # 05-045-18850  
Inspection # 696600338



Photo # 12 Trash on location



Photo # 13 Trash on location