

Inspection Photos

API: 05-071-06639

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/15/2019

Inspection Photos



Photo 1. Facing northeast toward the access road.

Inspection Photos



Photo 2. Facing northeast toward along the access road.

Inspection Photos



Photo 3. Facing northeast toward along the access road.

Inspection Photos



Photo 4. Facing east toward the location.

Inspection Photos



Photo 5. Transect Reclaim on location facing NE.



Photo 6. Transect Reclaim on location facing SW.

Inspection Photos



Photo 7. Transect Reference facing NE.



Photo 8. Transect Reference facing SW.

Inspection Photos

[illegible]

Photo 9. Transect Data