

Inspection Photos

API: 071-09651

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/15/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

I-API: 071-09651 | Date: 7/15/2019

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-09651 | Date: 7/15/2019

Inspection Photos



Photo 2. Pipe riser remains near the location. Pipe riser needs to be removed per the condition of approval.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-09651 | Date: 7/15/2019

Inspection Photos



Photo 3. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-09651 | Date: 7/15/2019

Inspection Photos



Photo 4. Facing east at the location along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-09651 | Date: 7/15/2019

Inspection Photos



Photo 5. Facing toward the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-09651 | Date: 7/15/2019