

Inspection Photos

API: 071-08762

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

I-API: 071-08762 | Date: 7/15/2019

Inspection Photos



Photo 1. Facing north along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-08762 | Date: 7/15/2019

Inspection Photos



Photo 2. Facing north toward the location. Road continues past the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-08762 | Date: 7/15/2019

Inspection Photos



Photo 3. Facing northeast toward at the location. Vegetation is not establishing in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-08762 | Date: 7/15/2019

Inspection Photos



Photo 4. Facing back to the southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-08762 | Date: 7/15/2019

Inspection Photos



Photo 5. There were a few noxious weeds beginning to establish.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-08762 | Date: 7/15/2019