

Inspection Photos

API: 071-07262

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/15/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

I-API: 071-07262 | Date: 7/15/2019

Inspection Photos



Photo 1. Facing south at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-07262 | Date: 7/15/2019

Inspection Photos



Photo 2. Facing southeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-07262 | Date: 7/15/2019

Inspection Photos



Photo 3. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-07262 | Date: 7/15/2019

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-07262 | Date: 7/15/2019

Inspection Photos



Photo 5. There north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-07262 | Date: 7/15/2019

Inspection Photos



Photo 6. Facing toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-07262 | Date: 7/15/2019