

Inspection Photos

Location Name: FOSS - USX AA-66N63W /5SWSW

Location #: 306382



Colorado Oil & Gas Conservation Commission
40.51179, -104.46557, 1421.0m, 115°
06/21/2019 04:09:25 PM

Photo #1

Foss - USX AA 5-25 (05-123-24562) Wellsite

Temporarily Abandoned | TA

Posted Emergency Number is NOT valid

***Weeds remain at wellsite
from prior insp.***



Colorado Oil & Gas Conservation Commission
40.51181, -104.46568, 1410.0m, 92°
07/17/2019 12:07:33 PM

Photo #2

Foss - USX AA 5-25 Wellsite

Temporarily Abandoned | TA

Valid Emergency Number NOW posted

Weeds appear mitigated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FOSS - USX AA-66N63W /5SWSW

Location #: 306382



Photo #3

Foss - USX AA 5-11, 5-25 Battery site

Abandoned

All equipment removed

from prior insp.