

Inspection Photos

07/17/2019

Operator: H & M PETROLEUM CORPORATION

10032

Location ID: 312312

Logan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312312



Photo 1: Photo taken from the east end of the location, facing west. Photo shows battery facility and pits have been closed, equipment removed and reclamation conducted. Though germination is evident, location is predominantly undesirable weedy plant species.



Photo 2: Photo taken from the east end of the pits, facing west. Photo shows pits have been closed. Though germination is evident, location is predominantly undesirable weedy plant species.

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312312



Photo 3: Photo taken from the southwest end of the pits, facing north. Photo shows area of the pits where desirable germination is not evident.



Photo 4: Photo taken from the southwest end of the pits, facing east. Photo shows area of the pits where desirable germination is not evident.

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312312



Photo 5: Photo taken from the location. Photo shows grass germination.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources