

Inspection Photos

07/17/2019

Operator: H & M PETROLEUM CORPORATION

10032

Location ID: 312318

Logan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312318



Photo 1: Photo taken from the south end of the location, facing north. Photo shows equipment has been removed, however, no other reclamation activities appear to have been conducted.



Photo 2: Photo taken from the location. Photo shows gravel/road base remaining on location. Equipment has been removed, however, no other reclamation activities appear to have been conducted.

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312318



Photo 3: Photo taken from the east end of the location, facing northwest. Photo shows equipment has been removed, however, no other reclamation activities appear to have been conducted.



Photo 4: Photo taken from the east end of the location, facing southwest. Photo shows equipment has been removed, however, no other reclamation activities appear to have been conducted.

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312318



Photo 5: Photo taken from the location. Photo shows gravel/road base remaining on location. No other reclamation activities appear to have been conducted.



Photo 6: Photo taken from the access road, facing northwest. Photo shows stormwater erosion degradation evident. Photo also shows reclamation activities, including but not limited to, compaction alleviation, recontouring/regrading and revegetation activities have not been conducted.

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312318



Photo 7: Photo taken from the where the well access road intersects with the main access road. Photo shows access road has not been reclaimed.



Photo 8: Photo taken from the where the well access road intersects with the main access road. Photo shows access road has not been reclaimed.

Inspection Photos

Operator Name: H & M PETROLEUM CORPORATION # 10032

Location ID: 312318



Photo 5: Photo taken from where the access road travels across a drainage. Photo shows access road has not been reclaimed. The drainage will require restoration including reclamation of the road, recontouring, regrading and revegetation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources