

# Inspection Photos

07/17/2019

Operator: BRITISH AMERICAN OIL PROD CO -  
#10558 / Chevron USA INC - Operator  
#16700

Location ID: 389108  
Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 1:** Image and comments taken from photo document #682502748: Current aerial imager (2015) showing well location and the former battery location. Red polygon represents area of the former battery and areas where degradation is evident either due to improper reclamation or stormwater runoff onto adjacent lands. Debris was observed scattered throughout this area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 2:** Photo taken from the well location, facing west. Photo shows riser remaining at location. Photo also shows location remains bare and exposed soil. Unable to find evidence that reclamation has been conducted per corrective actions.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 3:** Photo shows riser remaining at location. Unable to find evidence that reclamation has been conducted per corrective actions.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 4:** Photo taken from the south end of the former battery location. Photo shows trash debris and risers have been removed. Location remains bare and exposed soil. Unable to find evidence that reclamation has been conducted per corrective actions.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 5:** Photo taken from the east end of the battery location, facing southwest. See comments under photo 4.

## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 6:** Photo taken from the east end of the battery location, facing northwest. See comments under photo 4.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: BRITISH AMERICAN OIL PROD CO - #10558 / Chevron USA INC - Operator #16700

Location ID: 389108



**Photo 7:** Photo taken from the adjacent reference area. Photo shows well and battery location is not reflective of the reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources