

# Final Reclamation Inspection

July 17, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-11497

Inspection Document #: 697500346

Weld County, CO

SWNW Section 18 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GENESIS #2  
API: 05-123-11497



Google Earth aerial imagery taken 6/19/2014. Aerial imagery indicates the well location and access road appear to meet Rule 1004 standards. Field Inspection Report Doc. #200054044 conducted on 5/7/2004 passed Final Reclamation.

Inspection Photos  
Location Name: GENESIS #2  
API: 05-123-11497



Google Earth aerial imagery taken 9/7/2016. Well was re-plugged by another Operator (Kerr McGee) on 9/2/2016 to comply with current rules and regulations. Since the well location passed Final Reclamation previously it is the responsibility of Kerr McGee to meet Rule 1004 standards.

Inspection Photos  
Location Name: GENESIS #2  
API: 05-123-11497




**Photo 1.** Photo taken from the western access road, facing South. Photo illustrates access road is not reflective of reference crop areas.



**Photo 2.** Photo taken from a portion of the access road, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: GENESIS #2  
API: 05-123-11497



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: GENESIS #2  
API: 05-123-11497



**Photo 4.** Reference photo taken southwest of well location, facing West. See comments under Photo 1.