

Inspection Photos
Location Name: Margil 34-A
Location ID: 424006



Colorado Oil & Gas Conservation Commission
40.27344, -104.99456, 1541.0m, 201°
07/18/2019 12:17:54 PM

Location

Inspection Photos
Location Name: Margil 34-A
Location ID: 424006



Crude oil tank placarding on 2/22/19



Crude oil tank placarding on 7/18/19

Inspection Photos
Location Name: Margil 34-A
Location ID: 424006



Produced water vault placarding on 2/22/19



Produced water vault placarding on 7/18/19

Inspection Photos
Location Name: Margil 34-A
Location ID: 424006



Lease road on 2/22/19



Lease road on 7/18/19

Inspection Photos
Location Name: Margil 34-A
Location ID: 424006



Lease road on 2/22/19



Lease road on 7/18/19

Inspection Photos
Location Name: Margil 34-A
Location ID: 424006



Unused equipment on 2/22/19



Unused equipment on 7/18/19