

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 1. Location.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 2. Gas leak at separator.