

Maralex Resources Inc.
API # 05-077-08493
Inspection # 696600343



Photo #1 Photo of Battery sign at tank



Photo #2 Photo at location entrance

Maralex Resources Inc.
API # 05-077-08493
Inspection # 696600343



Photo #3 Photo of Tank battery and sign



Photo #4 Photo of wellhead

Maralex Resources Inc.
API # 05-077-08493
Inspection # 696600343



Photo # 5 Parts from separator on ground at time of inspection.



Photo # 6 Separator out of service , part on the ground at time of inspection.